

Leaks in the connection between soaker hose and drip tray

Sometimes, due to variations in the manufacture of the drain hose, the diameter of the inner pipe opening is large. This results in a loose connection between the drip cap and the drain hose, causing over-irrigation near the connection and a lack of water elsewhere.

There's a simple solution to this problem, using short lengths of standard 3.5mm Irrigation Irrigation tubing.



Use a piece of pipe about 4cm long with one end cut at an angle.



Push the square cut end through the drip tray outlet.



Press the bent end firmly into the drain hose.

This process must then be repeated for the stopper if it is used on a single length.



Use a piece of tubing about 4 cm long and press on the stopper.



Insert the other end into the drain hose.



Irrigatia Ltd, Norwoods, Long Drax, Selby, YO8 8NH, United Kingdom enquiries@irrigatia.com

www.irrigatia.com www.irrigatia.com